

BUILDING SAFETY CERTIFICATE

No. 94

Dated: 03/06/2026

It is certified that the eisting building GURU GOBIND SINGH KHALSA PUBLIC SCHOOL at Nandanvan road, Near Rungta College, Hathbandh, Raipur (C.G.) is having TWO block(s) in G+2 floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+2	G+2				

The building is owned/occupied by GURU GOBIND SINGH KHALSA PUBLIC SCHOOL have complied with the Building safety requirements in accordance with National Building Code Rules, and verified by the officers concerned of RURAL ENGINEERING SERVICE on 03/06/2026 in the presence of Smt. JAGRITI DUBEY, PRINCIPAL and that the building/premises is fit for occupancy for running school with effect from 03/06/2026 for a period of ONE years in accordance with rule and subject to compliance of the specific conditions as appended.

1. In Normal Condition.
2. In Normal Condition.
3. In Normal Condition.
4. In Normal Condition.

Issued on - 03/06/2026 at DHARSIWA by

Signature with Seal:

Name: RAJENDRA KUMAR SHUKLA ABHISHEK TAMRAKAR
Designation: SUB ENGINEER SUB DIVISIONAL OFFICER
Name & Address of Office: RURAL ENGINEERING SERVICE, SUB DIVISION - DHARSIWA

Principal
Guru Gobind Singh
Khalsa Public School
Hathband, Raipur