Annexure D

BUILDING SAFETY CERTIFICATE

No. **94** Dated: **03/06/2026**

It is certified that the eisting building **GURU GOBIND SINGH KHALSA PUBLIC SCHOOL** at **Nandanvan road, Near Rungta College, Hathbandh, Raipur (C.G.)** is having **TWO** block(s) in **G+2** floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	**G+2**	**G+2**				

The building is owned/occupied by **GURU GOBIND SINGH KHALSA PUBLIC SCHOOL** have complied with the Building safety requirements in accordance with National Building Code Rules, and verified by the officers concerned of **RURAL ENGINEERING SERVICE** on **03/06/2026** in the presence of **Smt. JAGRITI DUBEY, PRINCIPAL** and that the building/premises is fit for occupancy for running school with effect from **03/06/2026** for a period of **ONE** years in accordance with rule and subject to compliance of the specific conditions as appended.

1. In Normal Condition.
2. In Normal Condition.
3. In Normal Condition.
4. In Normal Condition.

Issued on - **03/06/2026** at **DHARSIWA** by

Signature with Seal:

Name: **RAJENDRA KUMAR SHUKLA** **ABHISHEK TAMRAKAR**
Designation: **SUB ENGINEER** **SUB DIVISIONAL OFICER**
Name & Address of Office: **RURAL ENGINEERING SERVICE, SUB DIVISION DHARSIWA**